



POTTER COAL AND  
COKE MINE

LEGEND

■ NPDES DISCHARGE POINTS		
001	AMD Plant Discharge	To Be Stopped
002	No. 1 Shaft Discharge	Stopped
003	No. 2 Shaft Discharge	Stopped
004	No. 4 Shaft Discharge	To Be Stopped
005	No. 5 Shaft Discharge	Stopped
006	No. 2 Shaft Sewage Treatment Discharge	Stopped
007	Tipple Runoff No. 1 - Not Shown	To Be Stopped
008	Tipple Runoff No. 2 - Not Shown	To Be Stopped
009	Refuse Pile Treated Discharge	To Continue
010	No. 6 Shaft Discharge	To Be Stopped
011	No. 6 Shaft Slope Runoff	To Be Stopped
001	No. 6 Shaft Sewage Treatment Plant	To Be Stopped
○ SURFACE WATER MONITORING POINTS		
A.	Upstream A.M.D. Plant Discharge	
B.	Downstream A.M.D. Plant Discharge	
C.	Downstream Slope Area Runoff	
D.	Downstream No. 5 Shaft Discharge	
▲ GROUNDWATER MONITORING POINT		
1.	Monitoring Well No. 1	
2.	Monitoring Well No. 2	
● MINE OPENING		
— PERMIT BOUNDARY		



I, the undersigned, hereby certify that this map is correct and shows all the information, to the best of my knowledge and belief, required by the mining laws of this state, and covers the period ending

THE HELEN MINING COMPANY  
BOWER CITY MINE  
Blacklick, Center, Burrell, Conesago Townships  
Indiana County  
Upper Freeport "K" Coal Seam Scale 1" = 400'  
Map Posted to January 31, 1993  
FINAL MINE MAP  
EAST 5100