



LW 15
LW 16
Not Shown!
See 372063

LEGEND

NDRES DISCHARGE POINTS	
001 AMD Plant Discharge	To Be Stopped
002 No. 1 Shaft Discharge	Stopped
003 No. 2 Shaft Discharge	Stopped
004 No. 4 Shaft Discharge	To Be Stopped
005 No. 5 Shaft Discharge	Stopped
006 No. 2 Shaft Sewage Treatment Discharge	Stopped
007 Tipple Runoff No. 1 - Not Shown	To Be Stopped
008 Tipple Runoff No. 2 - Not Shown	To Be Stopped
009 Refuse Pile Treated Discharge	To Continue
010 No. 6 Shaft Discharge	To Be Stopped
011 No. 6 Shaft Site Runoff	To Be Stopped
001 No. 6 Shaft Sewage Treatment Plant	To Be Stopped
SURFACE WATER MONITORING POINTS	
A. Upstream A.M.D. Plant Discharge	
B. Downstream A.M.D. Plant Discharge	
C. Downstream Slope Area Runoff	
D. Downstream No. 5 Shaft Discharge	
GROUNDWATER MONITORING POINT	
1. Monitoring Well No. 1	
2. Monitoring Well No. 2	
MINE OPENING	
PERMIT BOUNDARY	



I, the undersigned, hereby certify that this map is correct and shows all the information, to the best of my knowledge and belief, required by the mining laws of this state, and covers the period ending January 31, 1993.

RECEIVED

THE HELEN MINING COMPANY
HONOR CITY MINE
Blacklick, Center, Burrell, Conesauh Townships
Indiana County

Upper Freeport "E" Coal Seam Scale 1" = 400'
Map Posted to January 31, 1993
FINAL MINE MAP
WEST SIDE