



D. LLOYD
43A

MIRA STALB
25A 14P.

G. W. LLOYD
146P.

J.L. BAUM

HENRY LLOYD
12A.

JOHN LANTZY
120A 34P.

JOHN LANTZY
123A 13P.

Faulty Area --- 84 A
Previously Reported --- 40 A
To Be Reported --- 74 8/4

PORTER COAL
D' SEAM
WORKINGS

Lease Line

FARBER EST.
57A 52P.

HOPKINS & IRWIN
830 A.

ROBERT KILDEA
700 A

D.R. GOOD
48 A. 109P.

JOHN WHITED
93.4 A 103P.

JOHN
12

SUS. TWP

ELDER TW

BT-7011

Rich Hill No.5 Drift (E' Seam)

D' Seam Outcrop

E' Seam Outcrop

C' SEAM
Outcrop

Consolidated
D' Seam

Rich Hill
E' and D'

FACE-4/151

D.D.H.

Rich Hill
E' and D'

DDH
SUR 1777.5
E 1517.8
D 14957

Bone 7"
coal 3"
Binder 3"
Bone 5"
coal 5"

Rich Hill
E' and D'

Rich Hill
E' and D'

No. 10 D.D.H. "E"
SUR 1500.1
Coal 1573.2
3m. 3"

No. 9 D.D.H. "E"
SUR 1499.9
Coal 1573.2
3m. 3"

No. 8 P.H. "E"
SUR 1500.0
Coal 1573.2
3m. 3"

No. 5 P.H. "E"
SUR 1516.3
Coal 1573.2
3m. 3"

No. 13 P.H. "E"
SUR 1552.2
Coal 1573.2
3m. 3"

No. 12 P.H. "E"
SUR 1609.3
Coal 1573.2
3m. 3"

No. 11 P.H. "D"
SUR 1372.2
Coal 1573.2
3m. 3"

No. 14 D.H. "E"
SUR 1613.16
Coal 1573.2
3m. 3"

No. 15 D.D.H. "E"
SUR 1573.2
Coal 1573.2
3m. 3"

No. 17 D.H. "E"
SUR 1555.5
Coal 1573.2
3m. 3"

No. 18 D.H. "C"
SUR 1515.2
Coal 1573.2
3m. 3"

No. 2 D.D.H. "E"
SUR 1597.7
Coal 1573.2
3m. 3"

No. 22 D.D.H. "E"
SUR 1617.3
Coal 1617.3
3m. 3"

No. 16 D.H. "D"
SUR 1554.4
Coal 1573.2
3m. 3"

No. 21 P.D.H. "E"
SUR 1622.9
Coal 1622.9
3m. 3"

No. 19 D.D.H. "E"
SUR 1537.7
Coal 1573.2
3m. 3"

No. 1 P.H. "C"
SUR 1541.1
Coal 1541.1
3m. 3"