



VENTILATION SYMBOLS			
(F) = Main Fan	⊠ = Air Bridge	⊠ = Regulator	✕ = Man Door
○ = Auxiliary Fan	⊠ = Regulator	V = Velocity, fpm	Q = Quantity, cfm
→ = Air Flow - Intake	⊠ = Regulator	+	WG = Water Gauge
→ = Air Flow - Exhaust	⊠ = Regulator	+	
+ = Permanent Stopping	⊠ = Regulator	+	
+ = Temporary Stopping	⊠ = Regulator	+	

MINE MAP 36-05022
Showing the location and extent of development of the Post Coal Co. mine. Situate on the N. dip Primrose Vein, Conyngham Twp., Columbia County, Pa.
A.B. Riedel, P.E. 9/10/85
Scale 1"=100'