




VENTILATION SYMBOLS	
(F) = Main Fan	[] = Air Bridge
(A) = Auxiliary Fan	[R] = Regulator
[] = Air Flow - Intake	[+] = Man Door
[] = Air Flow - Exhaust	V = Velocity, fpm
+ = Permanent Stopping	Q = Quantity, cfm
+ = Temporary Stopping	WG = Water Gauge

MINE MAP
Showing the location and extent of development of the Burnside Mining Co. slope mine. Situate on the north dip Number 9 Vein, Coal Township, Northumberland County, PA.
A.B. Riedel, P.E. September 21, 1989
XD 36-06724 Scale 1"=100'

Alfred B. Riedel