




VENTILATION SYMBOLS			
⊙	= Main Fan	⊞	= Air Bridge
○	= Auxiliary Fan	⊞	= Regulator
→	= Air Flow - Intake	+	= Man Door
←	= Air Flow - Exhaust	V	= Velocity, fpm
+	= Permanent Stopping	Q	= Quantity, cfm
-	= Temporary Stopping	WG	= Water Gauge

MINE MAP
No. 2 Slope 36-06724
Showing the location and extent of development of the Burnside Mining Co. slope mine. Situate on the north dip #8 Vein, Coal Twp., Northumberland County, Pennsylvania.
A.B. Riedel, P.E. September 25, 1987
Scale 1" = 100'

ayfardBlind