



VENTILATION SYMBOLS (where appropriate)	
	Main Fan
	Auxiliary Fan
	Air Flow-Intake (Green)
	Air Flow-Return (Red)
	Stopping
	Air Bridge
	Regulator
	Man Door
	Velocity, fpm
	Quantity, cfm
	Water Gauge, in
	Escapeway
	Bleeder Removal Point
	Pillar Removal or Robbing
	Mine Seal
	Active Workings (Yellow)
	Curtain or Brattice
	Workings Not Surveyed
	Caved Ground



LONGITUDINAL SECTION

Through Mine Workings of the
Brookside Coal Company
situate in
Hegins Township, Schuylkill County

Alfred B. Kneel