

A diagram showing a 2nd level gangway with an Orchard Vein. The gangway is inclined at 38° to the horizontal. The distance along the gangway is 945.0, and the distance along the vein is 1046.0.

Middle Creek Mine Pool Elev.

property of ANTHRA-SOURCES

REILLY TOWNSHIP
FRAILEY TOWNSHIP

-  - Intake Air
-  - Return Air
-  - Escapeway
-  - Exhaust Fan
-  - Slope Entrance
-  - Permanent Stopping
-  - Temporary Stopping
-  - Overcast

- (1) No maps currently available on mines above and below
- (2) Middle Creek mine pool elevation 795 MSL

1140.0

HORIZONTAL/VERTICAL CONTROL POINT 1

property of ROBERT VESAY

HORIZONTAL/VERTICAL CONTROL POINT 2

U.S.G.S. BENCH MARK 906.0

Located along T - 571

MOUNTAIN RUN ENTERPRISES
ORCHARD VEIN SLOPE
M.S.H.A. I.D. NO. 36-7864

M.J. RODAK & ASSOCIATES

CAMP HILL, PA.

FRAILEY TOWNSHIP

DATE: 7/90

SCHUYLKILL COUNTY

SCALE 1" = 100'

1361