

VENTILATION MAP

Showing the coursing of the ventilating current at the Little Buck Mountain Coal Company slope mine. Situate on the north dip Skidmore vein (known locally as Little Buck Mountain) Tremont Township, Schuylkill County.

A.B. Riedel, P.E.

July 17, 1991
Scale 1"=100'

VENTILATION SYMBOLS	
(F)	= Main Fan
(A)	= Auxiliary Fan
→	= Air Flow - Intake
⇝	= Air Flow - Exhaust
— — —	= Permanent Stopping
—X—X—X	= Temporary Stopping
— — —	= Air Bridge
R	= Regulator
V	= Man Door
V	= Velocity, fpm
Q	= Quantity, cfm
WG	= Water Gauge
(E)	= Escapeway
BEP	= Bleeder Evaluation Point

