

DISCLAIMER: This map is provided as a courtesy to the Pennsylvania Bureau of Deep Mine Safety by American Premier Underwriters, Inc. (PMA The Penn Central Railroad Corporation) and its subsidiary United Railroad Corp., which own or control, but do not operate, the coal assets depicted herein.

American Premier Underwriters, Inc. and United Railroad Corp. disclaim any representation or liability to any person as to the accuracy or completeness of this map or its use for any particular mining, safety or non-safety related purpose. Any person who uses this map for any reason undertakes an independent duty to verify its accuracy and completeness. American Premier Underwriters, Inc. and United Railroad Corp. and their respective officers, shareholders, directors, officers and employees herewith from damage or liability arising from its use.

W. & H.L. SHORT

F. WIDDOWSON

P. HOUCK

J. HOUCK

K. KIRKLAND

FAULTED AREA

D-F EXTENSION

D. WIDDOWSON

USE TRACING

MATCH LINE

50 LINE BORER PILLAR

VERY BAD

ROOF BROKEN