



MAP showing the location of the COLLIERIES AND LATERALS in the MAHANAY AND SCHUYLKILL COAL FIELDS.

NAME OF OPERATOR NAME OF COLLIERY NAME OF COLLIERY NAME OF OPERATOR



NAME OF OPERATOR	NAME OF COLLIERY	NUMBER
A. S. Van Winkle	Coleraine	352
Silver Brook Coal Co.	Silver Brook	351
Abandoned	Foresters	306
	North Star	205
	Vulcan	201
	Indian Run	200
	Beaver Run	204
	Hillside	203
P. & R. Coal & Iron Co.	Tunnel Ridge	208
Abandoned	Stewardship	297
P. & R. Coal & Iron Co.	Mahanoy City	207
Abandoned	Schuylkill	205
P. & R. Coal & Iron Co.	North Mahanoy	206
Abandoned	Elmwood	206
P. & R. Coal & Iron Co.	Boston Plain	214
	St. Nicholas	209
Abandoned	Suffolk	210
P. & R. Coal & Iron Co.	Bear Run	218
	Draper	215
	Maple Hill	318
	Blangowan	211
	Knickerbocker	212
	Gilterson	216
Abandoned	Wartha	304
Furnace Coal Co.	Furnace	217
Cambridge Coal Co.	Cambridge	308
P. & R. Coal & Iron Co.	Indian Ridge	293
P. & R. Coal & Iron Co.	Platt's Ridge	227
Thomas Coal Co.	Shenandoah City	226
Abandoned	Whaley Run & Washery	228
P. & R. Coal & Iron Co.	Centennial	305
Abandoned	West Shenandoah	224
P. & R. Coal & Iron Co.	Locust Mountain	307
	Kohunoor	225
	Turkey Run	223
	Laurel Ridge	314
William Penn Coal Co.	South Laurel Ridge	315
Abandoned	William Penn	222
P. & R. Coal & Iron Co.	Stanton	294
	West Bear Ridge	298
Lehigh Valley Coal Co.	Packer No. 2	221
Abandoned	Lawrence	218
Abandoned	St. Michael	250
P. & R. Coal & Iron Co.	Howard Mammoth	251
Abandoned	Conner & Washery	229
	Cuyler	232
P. & R. Coal & Iron Co.	Mammoth	299
Abandoned	L.V. Coal Co.	220
Lehigh Valley Coal Co.	Packer No. 1	220
P. & R. Coal & Iron Co.	Bear Ridge	219
W. P. M. Tark & Co.	Howard Washery	246
Abandoned	Preston No. 2	234
P. & R. Coal & Iron Co.	Preston No. 1	233
	Preston No. 3	247
Lehigh Valley Coal Co.	Continental	235
Abandoned	Preston No. 4	248
P. & R. Coal & Iron Co.	North Ashland	238
Abandoned	Wagle	239
L. A. Riley & Co.	Centabria	236
Abandoned	L. A. Riley & Co.	237
Abandoned	Hazel Dell	303
P. & R. Coal & Iron Co.	Gorrel's Upper Colliery	303
	Bast	240
Abandoned	Bug Mine Run	241
L. A. Riley & Co.	Logan	320
Abandoned	Little Mine Run	295
	Locust Run	245
Morris Ridge Coal Co.	Interprise	249
Abandoned	Morris Ridge	319
L.V. Coal Co.	Columbus (aband.)	322
Mid Valley Coal Co.	Mid Valley	325
Abandoned	Coal Ridge	253
	Ashland	250
	Cambrian	251
	Germanloun	292
Thos. M. Richter & Co.	Mt. Carmel	254
Abandoned	Tunnel	244
P. & R. Coal & Iron Co.	Potts	257
Union Coal Co.	Richards	324
Abandoned	Charter Oak Run	243
	Pioneer Run	242
P. & R. Coal & Iron Co.	Reliance	252
Abandoned	Keystone	258
Abandoned	Green Ridge	265
	Coal Mountain	266
	Merriam	256
Patton Anthracite Mining Co.	Natalie	323
P. & R. Coal & Iron Co.	Mt. Carmel Shale	302
Abandoned	Gordon	310
	Locust Gap	262
P. & R. Coal & Iron Co.	Monitor	255
Abandoned	Locust Summit	261
	A. S. Wolf	260
Union Coal Co.	Pennsylvania	317
P. & R. Coal & Iron Co.	Locust Gap	300
	Locust Spring Gap	259
Abandoned	Hollenstein	263
	Ben Franklin	264
Excelsior Coal Mining Co.	Excelsior	275
Abandoned	Brady	267
Excelsior Coal Co.	Corbin	327
Shorman Coal Co.	Lancaster (Colbert)	291
Union Coal Co.	Hickory Swamp	269
Abandoned	Greenback	276
Abandoned	Daniel Webster	284
Mineral RR & Mining Co.	Duke	270
Abandoned	Daniel Webster	284
	Gartland	271
Mineral RR & Mining Co.	Cameron	282
Abandoned	Clinton	282
L. Langdon Co.	McLendon	281
Abandoned	Marshall	290
P. & R. Coal Co.	Royal Oak	290
Abandoned	Shanklin	287
	Franklin	283
	Carson	512
P. & R. Coal & Iron Co.	Frank Gowen	280
	Peerless	313
	Stirling	309
	George Hales	289
P. & R. Coal & Iron Co.	Bear Valley	285
	Henry Clay	311
Abandoned	Henry Clay No. 2	277
P. & R. Coal & Iron Co.	Burkside	286
Abandoned	Buck Ridge	278
Abandoned	Big Mountain	279
Interprise Coal Co.	Interprise	273
Abandoned	Amory	272
	Mid Valley No. 2	272
P. & R. Coal & Iron Co.	North Franklin No. 2	230
Abandoned	North Franklin	288

NAME OF COLLIERY	NAME OF OPERATOR
Middle Lehigh	Abandoned
Morea	Mill Creek Coal Co.
Greenwood No. 2	Abandoned
Greenwood No. 1	Dodson Coal Co.
Burning Vein	Abandoned
Anthracite	
Alaska	
East Lehigh	Mitchell & Shepp
Allen	Dunkleberger & Co.
West Summit	A. Raabe
New Kirk	Abandoned
New Kirk	
Grampus	
Wabash	
Reevesdale	
Buckville	
Tuscarora	
Kentucky	
Swift Creek	
Peach Mountain	
Altamont	
Spruce Forest	
Mine Hill	
Sagular	
New Castle (Abandoned)	
Bureka	
St. Clair	St. Clair Coal Co.
Hickory	Abandoned
Peach Orchard	
Pine Forest Shaft	P. & R. Coal & Iron Co.
Coal Hill	Abandoned
Kaska William	Alliance Coal Mining Co.
Pine Dale	Abandoned
New Diamond	
Boyce Baltimore	
Buller	
Gale Vein	
Silver Creek	P. & R. Coal & Iron Co.
Franklin	Abandoned
Cedar Hill	
Palmer Vein	Alliance Coal Mining Co.
Wagle Hill Shaft	P. & R. Coal & Iron Co.
Glentworth	Abandoned
Peach Mountain	
Palmer Vein No. 1	
St. Clair	
Diamond	
Bear Ridge Switch	
Ravine	
Rainbow	
Feeder Dam	
Merion	Marion Coal Co.
Mill Creek	Abandoned
Ellsworth	John R. Davis
Red Ash	Abandoned
Wadesville Shaft	G. H. Troutman & Co.
Pottsville Collieries	P. & R. Coal & Iron Co.
Flowers Field	Abandoned
Diamond	Sturdevant
Peach Orchard	Geisweil
Crystal	Abandoned
White Oak	
Reverate	
Beechwood	P. & R. Coal & Iron Co.
York Farm	L.V. Coal Co.
Gale Vein	Abandoned
Oak Hill	
Pine Knot East	
Live Oak	
East Ridge	East Ridge Coal Co.
Mine Hill Gap	Abandoned
Dundas No. 1	P. & R. Coal & Iron Co.
Little Diamond	
Oak Hill	Leisenring & Co.
Cressonville	Abandoned
Pine Knot West	
Wolf Creek Diamond No. 1	Lawrence
Wolf Creek Big Diamond	Abandoned
Herbire	
Albright (Salem)	Albright Coal Co.
Great Western	Abandoned
Putner	
West West	
Black Mine	
Wolf Creek	
Wolf Creek	
North Phoenix No. 1	
Phoenix Park No. 2	P. & R. Coal & Iron Co.
Phoenix Park No. 3	Abandoned
Diamond	
Branch Dale	
Blackwood	L.V. Coal Co.
Phoenix Park No. 2	Abandoned
Old Heckscherville	P. & R. Coal & Iron Co.
Feger Ridge	
Dundas No. 6	
Forestville	P. & R. Coal & Iron Co.
Lytle	Lytle Coal Co.
Leur's Vein	Abandoned
Otto	P. & R. Coal & Iron Co.
Swarara	Abandoned
Thomaston	
Swarara North	
Thomaston	P. & R. Coal & Iron Co.
Kemble	Abandoned
Anchor Washery	P. & R. Coal & Iron Co.
Oakdale	Abandoned
Middle Creek Shaft	P. & R. Coal & Iron Co.
Richardson	P. & R. Coal & Iron Co.
Glendower	
Taylorville	Abandoned
Taylorville	
North Pine Grove	
Lorberry	Loesch Moore & Co.
Colket	Abandoned
Rausch Creek East	P. & R. Coal & Iron Co.
Rausch Creek West	P. & R. Coal & Iron Co.
East Franklin	
Bureka	Abandoned
West End	
New Lincoln	
Hickert	
Lincoln	P. & R. Coal & Iron Co.
Hughens Summit	Abandoned
Good Spring	P. & R. Coal & Iron Co.
Pine Hill	Cochran & Co.
Williams	Williams Coal Co.
East Brookside	P. & R. Coal & Iron Co.
Kalmia Washery	P. & R. Coal & Iron Co.
West Brookside	P. & R. Coal & Iron Co.
New Brookside	

Middle or Mahanoy Coal Field

Southern or Schuylkill Coal Field