



11-2-24	W.C.S.
9-21-26	W.C.S.
3-21-27	W.C.S.
7-27-27	W.C.S.
1-1-28	W.C.S.
7-7-30	W.C.S.
1-17-31	W.C.S.
5-18-31	W.C.S.
7-31-32	W.C.S.

SOUTHERN FIELD
SHERMAN COLLY. ALL VEINS

STATE MINE INSPECTOR'S
MAP
SHERMAN COAL CORPORATION
mine workings - POTTSVILLE, PA.