

53-33

J. B. Schooley Estate 78

Wyoming Land Company 79b

Heirs of I. C. Shoemaker 1a

and

Heirs of W. S. Shoemaker 2b

Payne Peitebone Est 8b

Heirs of I.C. Shoemaker 1c

0.21 1/2 of Barrier Pillar North of Fault on West Side of J.B. Schooley Est.
 1.12 - Wyoming Land Co. Lot 79B
 1.02 - I.C. Shoemaker Lot 1a & 2b
 1.55 - of Mt. Lookout Coal Co. can be mined.

1/2 of Barrier Pillar North of Fault on West Side of J.B. Schooley Est.
 1.12 - Wyoming Land Co. Lot 79B
 1.02 - I.C. Shoemaker Lot 1a & 2b
 1.55 - of Mt. Lookout Coal Co. can be mined.

1/2 of Available Coal North Side of Fault - this lot
 2.30 - Coal on straddling or fault
 1.50 - Barrier Pillar on West Side
 1.50 - Available Coal South side of fault
 Total 20.50 ft. in Tract (Hice Lot)

Center of Fault (Change in direction of ground)
 of Fault and Shale
 Available Coal 100 ft. high
 Coal 12 ft. thick

1/2 of Barrier Pillar South side of J.B. Schooley Est.
 0.50 - of Payne Coal Co. can be mined
 0.15 - of Payne Coal Co. can be mined
 0.15 - of Payne Coal Co. can be mined
 0.15 - of Payne Coal Co. can be mined

Perrin Coal Company

Hice Lot