




Hubbard Stock No. 7803  
 $1\frac{3}{8}$ " Dia.  $\frac{7}{64}$ " Thick, Galvanized  
 Round Washer with  $\frac{9}{16}$ " Hole.




Hubbard Stock No. 7814  
 $2\frac{1}{4}$ " x  $2\frac{1}{4}$ " Galvanized Square  
 Washer,  $\frac{3}{16}$ " Thick, with  $\frac{13}{16}$ " Hole




Hubbard Stock No. 7819  
 4" x 4" Galvanized Square Washer  
 $\frac{1}{4}$ " Thick with  $\frac{15}{16}$ " Hole



Hubbard Stock No. 7448  
 Galvanized Rolled Steel  
 2-Bolt Guy Clamp.



Hubbard Stock No. 6460  
 Flexible Ground Wire Clamp  
 Hot Galvanized.



Hubbard Stock #7495  
 "Copperweld" Staple  
 For fastening Ground  
 Wire to Pole

WASHERS, GROUND WIRE CLAMPS, STAPLES

ENGINEERING DEPARTMENT  
 SUSQUEHANNA COLLIERIES COMPANY  
 LYTLE COAL COMPANY

Wilkes Barre PA 10-9 1928 SCALE 1 FOOT

DRAWN BY EJD.

CHECKED BY \_\_\_\_\_

APPROVED [Signature]

DR. NO. 66-578

OK 8/20/11