


Penfield 6 78°30' 41°05' Clearfield 4 Clearfield 6 78°25' 41°05'

● ACTIVE OIL WELL	* ACTIVE OIL & GAS WELL	— COUNTY LINES	— 000 UF COAL CONTOURS
○ ABANDONED OIL WELL	* ABANDONED OIL & GAS WELL	— TOWNSHIP LINES	- - - CROP LINES - SEAM BEING MINED
* ACTIVE GAS WELL	◇ DRY HOLE	— BOROUGH LINES	- - - CROP LINES - SEAMS NOT BEING MINED
* ABANDONED GAS WELL	○ NO RECORD		



Curwensville 78°30' 41°00' Houtzdale 1 2 MILES CLEARFIELD SHEET No. 7 (E)-U. F. SEAM U. F. FREEDPORT

W.P.A. PROJECT NO 4483

Y	DRIFT OPENING
Z	SLOPE OPENING
□	SHAFTS
▣	BARRIER PILLAR