

Somerset 2  
40° 10'

Somerset 3

COUNTY LINES  
 TOWNSHIP LINES  
 BOROUGH LINES  
 COAL CONTOURS  
 CROP LINES-SEAM BEING MINED  
 CROP LINES-SEAMS NOT BEING MINED

79° 00'  
Windber 1  
40° 10'



Somerset 5

Windber 4

Somerset 8  
79° 05'

Somerset 9

2 MILES

MINE MAP DEPARTMENT. 1936.

E SEAM  
 SOMERSET SHEET NO. G.  
 UPPER FREEPORT 4f

40° 05'  
Windber 7  
79° 05'