



Matched

COUNTY LINES  
 TOWNSHIP LINES  
 BOROUGH LINES  
 COAL CONTOURS  
 CROP LINES - SEAM BEING MINED  
 CROP LINES - SEAMS NOT BEING MINED



Windber 2 78°50' 40°10'  
 Windber 5  
 Windber 8 78°50' 40°05'  
 MINE MAP DEPARTMENT 1936



Windber 3  
 Windber 9  
 Bedford 1  
 Bedford 4  
 Bedford 7  
 E-SEAM  
 2 MILES WINDBER SHEET NO. 6  
 UPPER FREEPORT - U.F.

Matched