

Neshaminy Creek Watershed

Lambertville Quadrangle



Forest Buffer Status

- Both Sides Lacking
- One Side Lacking
- Partial Buffer

Aerial Photograph Index

Neshaminy Creek Watershed Boundary

Source:
Heritage Conservancy, Penn State
University (PASDA), US Geological
Survey, DVRPC.



PREPARED BY:
Heritage Conservancy
85 Old Dublin Pike
Doylestown, Pa 18901
215-345-7020
www.heritageconservancy.org
January 2001



FUNDED BY:
PA DEP as part of the
Coastal Zone Management
(CZM) Program.

The information conveyed in this map is regional in nature
and is not suited for site specific studies. The user shall hold
Heritage Conservancy harmless from any suits, claims or
actions arising out of the use of this map or accompanying
documentation.

