



MAP OF COAL MINES  
OF THE  
STATE NORMAL  
SITUATE IN  
Slippery Rock Boro, Butler Co., Pa.

Scale 1 inch = 100 FT  
Surveyed 1920  
L. J. Taylor Engineer Slippery Rock Pa.

G. WILSON

G. WILSON

RECEIVED IN DEP. AGREEMENT  
AMOUNT OF MINABLE COAL WEST OF  
PROPOSED RESERVE LINE APPROXIMATELY 44'

PROPOSED EXTENSION TO CENTER STREET  
APPROXIMATE

VINCENT & PATTERSON

GERLACH BRO'S

APPROXIMATE MAIL ANGLE CORN

B.M. on oak tree  
1319.33

WATER TANK  
EMERGENCY HOUSE

OLD WORKS PATTERSON MINE

30 BALL PAKK

CENTER ST.