



WATER SAMPLES: Background & Monitoring

No.	Source	Date	pH.	SC.	Elev.	Flow
*1	Lesle Run	4/4/83	4.5	550	1645	150
*2	Lesle Run	4/4/83	6.5	290	1760	20
3	Deep Mine Discharge	4/4/83	7.0	415	1850	3

* PROPOSED MONITORING POINT

* 1 SAMPLE NO. 1 IS LOCATED APPROXIMATELY 3000 FEET DOWN STREAM.

- 2.0 Ac. Mining-Spoil Area
- 3.0 Ac. Reclamation-Support Area
- 5.0 Ac. TOTAL

MODULE - 6

E. P. BENDER COAL COMPANY
SPECIAL RECLAMATION PROJECT
 SITUATE
 WEST CARROLL TWP., CAMBRIA CO., PA.

SCALE 1" = 200'	GWIN, DOBSON & FOREMAN, INC. CONSULTING ENGINEERS ALTOONA · PENNSYLVANIA	SHEET NO.
--------------------	---	-----------