



Eureka No. 5 Workings.

Located and copied from blueprint of B-W. Map.
 Note: - Map is not known to show the exact limit of the workings, and a sufficient barrier pillar must be left for safety of No. 6 workings. Careful inspection to discover "bleeding" at the working face, should be made frequently.

No workings allowed in this area.
 Rooms may extend to this line unless
 bad roof develops
 Ramp out over
 Sights for Last Room
 N 82 1/2° E

About 30' of cover
 (B-W. data.)

PUNXS. C. M. CO.
 Eureka No. 6. (partial map)

Showing workings in vicinity of Mahoning Creek and Eureka No. 5.
 Scale 1"=100'
 Punxsutawney, Pa., Aug. 10, 1917. H.M. Kanarr Engr.

young top., Jefferson County
 Valer-Punxy grade

Note: - Shaded parts indicates work done prior to last survey. Faint lines shows work traced from blueprints of the B-W.C.M. Co. mine map, and is subject to correction. Projections revised to agree with the findings of the Inspector's Commission on Nov. 13, 1917.

2-A-16

STE-38