Outcrop
Outcrop
Outcrop
Outcrop
No.3 Mine
No.2 Mine
No.1 Mine
Magazine
Abandoned
Furnace Shaft Abandoned
Manway
Main
Fan shaft abandoned
Boilers
Barn
Store
1st Left
2nd Left
3rd Left
Main or 5th
Crawley Drift
1390

MINES OF THE

Kettle Creek Coal Mining Co.

BITUMEN, CLINTON COUNTY, PA.

GEO. L. MILLER, GENERAL MANAGER

Scale 100 Feet = 1 Inch

Note: Add 1300 to elevations in mines to get Sea Level Datum.

▨ shows pillars drawn.

Survey Carried Forward to July 1st 1901 by Geo. L. Miller Engr.
~~Jan. 1st 1902.~~
~~July 1st 1902.~~
~~Jan. 1st 1903.~~
~~July 1st 1903~~
~~January 1st 1904~~
~~July 1st 1904~~
~~Jan. 1st 1905~~
~~July 1st 1905~~
~~Jan. 1st 1906~~
~~Septr 15th 1906.~~
~~April 1st 1907~~
Nov. 1st 1907.
July 1st 1908 – Practically no work excepting a few Pillars in No 1.
Jan 1st 1909 " " " " " " "
July " 1909 " " " " " " "
Jan. 1910 " " " " " " "
July 1910 " " " " " " "

May 23, 1929 – By O.B. Hess, R.P.E. – Office of E. W. Hess, Engr., DuBois, Pa.

MINE No 2 – ABANDONED, SEPTEMBER 15, 1929.

I hereby certify that, to the best of my knowledge and belief, this is a true and correct copy of the original map of PART OF Mine No 2, and that the original map is a true, complete and correct map and survey of all excavations made in this mine
O.B. Hess, Reg. Engr.