



NOTE:-  
 ELEVATIONS TAKEN FROM  
 DATUM AT DRAUCKER MINE.  
 First mud sill Dra. mine 1088.1

<b>CRESCENT REFRACTORIES CO.</b>		
CURWENSVILLE, CLEARFIELD COUNTY, PA.		
ENGINEERING DEPARTMENT		
MAP SHOWING THE LOCATION OF DIAMOND DRILL HOLES ON THE PROPERTY OF JOHN WELLS.		
DRAWN <i>R.A.</i>	SCALE 1"=100'	<b>1075-I</b> 50-3-136
CHECKED	DATE Oct 22 1927	
REFERENCE	ORDER	