DDH #7 BLANK

DDH #8 FAULTY

DDH #2 N.G.

Fence Corner

Old Barbwire Fence

DDH #130 No Clay

DDH #129 3'5" Good Block 5'6" Irony Bot. N.G.

DDH #131

DDH #133 1' Black Shell 2' Dark Block 6'5" S.C N.G.

DDH #132 3' Black Shell 2' Good Block

DDH

Bore Hole #3

DDH ? 1038.8

DDH ? 1037.8

Woods

Woods Line

Old Woods Road

Boulders

Ledge

Roof Rock

along top of ledge

SWAMP RUN

Spring

P.P.H. 1024.3

PPH 1006.3

PPH 1010.5

PPH

PPH 1002.0

Old coal Drift

Old Clay Drift

Old coal Drift

Drift

Bottom of Ledge Stripping Line

Scave

Face

NORTH

Scale 1" = 100 Ft.

CRESCENT REFRACTORIES CO.
CURWENSVILLE, CLEARFIELD COUNTY, PA.
ENGINEERING DEPARTMENT

Drill Hole Record on Laurel Swamp Tract

DRAWN		SCALE	53-2-6
CHECKED		DATE	
REFERENCE		ORDER	