

REFERENCE DATA

BICKFORD FIRE BRICK COMPANY.

CURWENSVILLE, CLEARFIELD COUNTY, PA.

ENGINEERING DEPARTMENT

ENV. No 42

SHEET No 33

562-14
10

Clay Area - Irvin & Murray and Ross Bloom.

DATE Aug 18, 1915

Feb 27, 1919

Dec. 1-1919

SCALE 200' = 1"

D.D.H. 30
SURF. 1056.7
Bot. C. 1019.2
UNFINISHED

D.D.H. 32
SURF. 1086.4
Bot. H. 1023.9

D.D.H. 28
SURF. 1079.4
Bot. C. 1026.4

Ross Bloom

D.D.H. 12
SURF. 1059.1

D.D.H. 29
SURF. 1078.3
Bot. C. 1024.3

D.D.H. 31
SURF. 1048.1
Bot. C. 1011.5

D.D.H. 6
SURF. 1065.4
Bot. C. 1002.4



Crop Line

Irvin & Murray

D.D.H. 23
SURF. 1047.1
Bot. C. 991.1

D.D.H. 19
SURF. 1045.3

SURF. 1028.9
Bot. C. 973.7

SURF. 1020.4
Bot. C. 976.4

SURF. 1022.7
Bot. C. 967.7

D.D.H. 20
SURF. 1022.5

D.D.H. 25
SURF. 1024.5
Bot. C. 971.5

D.D.H. 26

D.D.H. 21
SURF. 1018.5
Bot. C. 967.4

Fault

air shaft

Clay

Discovered 1918

Clay Removed 1918

Crop Line