



Victim's head inside car as shown. Right shoulder pinned against left side of car. Left shoulder caught against roof. Apparently force of car on man's chest caused injury. Car was in motion when man got pinned between roof and car. Victim was attempting to couple cars when accident occurred.

STEVE SUMAK
 FATAL ACCIDENT
 BARNES & TUCKER CO.
 OLD NO. 10 MINE
 BARNESBORO, PA.

Scale 1" = 10' in #1
 1" = 3' in #2
 1" = 5' in #3
 March 9, 1942