



Insert Of Rock On Victim

Sketch of John Daisley Accident
 Lancashire No 15 Mine Barnes & Tucker Co
 Dec 14, 1962 1st Shift 9:00 A.M. Scale 1" = 20'
 John Daisley left Shuttle Car In Standby Position
 to inspect colmol position to determine if he
 could move shuttle car into loading position.
 Sudden collapse of roof pinned Daisley under
 rock which was partially supported by other
 shuttle car and colmol