



Place where victim was caught, under rock slab 'A' which broke away from main slab (24'-6" x 15'-6"). C.L. was most seriously hurt. The other victims W.W. was caught where shown. Props a, b, c, d and e were being prepared for setting up and were found in the position shown, after the rock fell.

Date of Injuries Sept. 25, 1937.

ROCK FALL ACCIDENTS  
 CONVEYOR ROOM PILLAR  
 BARNES COAL NO. 15,  
 BAKERTON, CAMBRIA CO., PA.  
 S.C. 1" = 4 FT. Sept. 29, '37