



Sketch Showing Fatal Accident  
 of  
 John Klamar  
 at  
 Springfield No 4 Mine  
 of  
 Barnes & Tucker Co  
 November 10, 1959 5:45 P.M.

Upon returning from the slope bottom with empties Frank Gomolka, a motorman, noticed the spillage around the car and the absence of the victim from his normal loading position. He immediately shut off the belt & summoned aid, then he started to dig in the spillage for the victim. Within minutes Ralph Lyons and Wm. Harkinish arrived and helped dig until the victim was found. Immediately after finding & uncovering the victim he was given artificial respiration but failed to respond. The victim was found lying under the conveyor with approximately 5 tons of coal covering him.