




BEAR ROCK MINING COMPANY
LILLY, PENNSYLVANIA
MAP TO ACCOMPANY
APPLICATION FOR SURFACE SUPPORT PERMIT
SHOWING AREA TO BE MINED, COLORED YELLOW
DECEMBER 27, 1964 J. KLEMSTINE

Mapped, edited, and published by the Geological Survey
Control by USGS and USC&GS
Topography by photogrammetric methods from aerial photographs
taken 1962. Field checked 1963
Polyconic projection. 1927 North American datum
10,000-foot grid based on Pennsylvania coordinate system, south zone
1000-meter Universal Transverse Mercator grid ticks,
zone 17, shown in blue
Fine red dashed lines indicate selected fence and field lines where
generally visible on aerial photographs. This information is unchecked

**CRESSON TOWNSHIP
CAMBRIA COUNTY
PERMIT NUMBER - 288-1
"B"-OR LOWER KITTANNING SEAM**



ROAD CLASSIFICATION
Heavy-duty ——— Light-duty ———
Medium-duty ——— Unimproved dirt ———

U.S. Route
State Route
Raymond S. Campbell
Reg. Engr.
CRESSON, PA.
NE/4 EBENSBURG 15' QUADRANGLE
N4022.5—W7830/7.5

THIS MAP COMPLIES WITH NATIONAL MAP ACCURACY STANDARDS
FOR SALE BY U.S. GEOLOGICAL SURVEY, WASHINGTON 25, D. C.
A FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST

1963
AMS 5264 1 NE—SERIES 7831