BLAIR & CAMBRIA
REALTY COMPANY.
APPROXIMATE EDGE OF FAULT
SWARTZ RUN
ROAD
MAIN SLOPE
2ND SOUTH
1ST SOUTH
1ST NORTH
2ND NORTH
3RD NORTH
3RD SOUTH
NEW SQUARE
MAIN
DIP
HEADINGS
FAULT
WORKED OUT
APPROXIMATE EDGE OF FAULTS
NO MAP OF FAULT SHOWING PACES OF THESE WORKINGS BY INFORMATION IS THAT WORKINGS WERE STOPED BY FAULT BEFORE REACHING PROPERTY LINE
DEXCAR COAL MNG. CO.
MAP OF
CLAIRE MINE
SECTION BELOW OLD THIRD RIGHT
AT ASHVILLE, CAMBRIA COUNTY, PA.
SCALE 1" = 100'
EXTENDED TO
CARPENTER CORPORATION
ALTOONA, PA.
I HEREBY CERTIFY THAT THIS MAP WAS BROUGHT UP TO DATE, EXCEPT IN THE OLD INACCESSIBLE WORKINGS IN 1ST AND 2ND RIGHT, ON JAN. 5TH 1928 WHEN PARTIALLY DRAWN.
MINING ENGINEER