

MINED OUT BY LLOYDVILLE MINE

APPROXIMATE LINE OF LLOYDVILLE



ORANGE BANK CUT

FAULT

FAULT

4 feet  
25 feet of main

HARBISON-WALKER REFRACTORIES CO.

MAP  
SHOWING WORKINGS OF B SEAM  
OF  
FRANK & MCCARTNEY COAL CO.  
SITUATE  
BLANDBURG, READE TWP., CAMBRIA CO., PA.  
SCALE 1" = 100'  
AUG. 1944.  
J.L. BANFIELD REG. SUR.

F&K COAL CO.  
F&K No. 1 MINE

11/64