JOHN MOLTON COAL CO., OPERATOR
"D" SEAM MINE
SITUATE: ADAMS TWP., CAMBRIA CO., PA.
SCALE: 1"= 100' April 15, 1968
Don Cortese
R.S. No. 2959-E
COMMONWEALTH OF PENNSYLVANIA
DON CORTESE
SURVEYOR
No. 2959 E
LEGEND
CONTEMPLATED MINING 4-15-68 to 10-15-68....
SUPPORT AREA.................... NONE
PROTECTED STRUCTURES.................. NONE
MINING COMPLETED AREA....................
LEASE LINE.............................
FIELD COPY
PENNA. DEPT. OF MINES
REC'D
JUN 13 1968
BUREAU OF MINE SUBSIDENCE
Mining Area From April 15, 1968 To Oct. 15, 1968
Lease Line
Lease Line
Lease Line
Lease Line
Barrier
S.77°17'E
953.7
967.2
S12°43'
40
40
ES A. LEAMER COAL
APPROX
"D" SEAM
CROP
LINE
N.62°20'W
639.72
268.80
N.62°
N.45°50'E
405.0
S.45°50'W
467.0
N.49°13'W
256.83
GF Huff Tract
Air Course
Drift
Faulty C=0.80
C=2.80
2-A
1-A
1-C
2-C
3-C
630.7