



I have carefully examined the mine map and the strata of several drill holes of the Vinton Colliery Mine No. 6, situate in Blacklick and Buffington Townships, Indiana County, Pennsylvania, and to the best of my knowledge and belief, feel that the mining of the coal seam as indicated, will not sufficiently disturb the overlying strata to be hazardous.

Walter C. Kinsley, P.E.
Mining Engineer

DRISCOLL MINING COMPANY
CRESSON, PENNSYLVANIA

MAP TO ACCOMPANY REQUEST FOR AUTHORIZATION TO MINE WITHIN THE SAFETY ZONE ESTABLISHED BY ACT 723 OF THE GENERAL ASSEMBLY.

SHOWING A PART OF THE WORKINGS OF DRISCOLL NO. 4 MINE, FORMERLY VINTON NO. 5 MINE, UNDER AND NEAR THE NORTH BRANCH OF BLACKLICK CREEK, IN THE "B" OR LOWER KITTANNING COAL BED.

SHOWING THE AREA TO BE MINED, AND THE PLANNED METHOD OF MINING.

LOCATED IN BLACKLICK TOWNSHIP, CAMBRIA COUNTY AND BUFFINGTON TOWNSHIP, INDIANA COUNTY, PENNSYLVANIA.

TRACED FROM THE VINTON NO. 6 200' MINE TRACING, BOREHOLE RECORDS TAKEN FROM THE FILES OF VINTON NO. 6

February 1, 1961

I have examined this mine map, together with attached columnar sections of the overlying strata, of Driscoll # 4 Mine (formerly Vinton # 5 Mine) and it is my opinion that the mining as projected hereon will not create an unusual condition within the "Safety Zone" and the plan is hereby approved for owner.

W. C. Kinsley
Mining Engineer for
Western Warehousing Company

SCALE 1"=200'

APPROVED

DEPARTMENT OF MINES AND METALLURGY

Secretary *Louis E. Evans* 3/4/61

Deputy Secretary *W. H. ...*

District Inspector *J. D. ...*

Mining Engineer *William C. Kelly*

ENGINEER
No. 4504
P.E.