..SOUTHERN COAL FIELD..
..NORTH SECTION..
OTTO COLLIERY..SKIDMORE VEIN..1"=100'..
REILLY Twp, Schuylkill County Branchdale Pa., 15·W. Schuylkill District..
READING ANTHRACITE Collieries.

West Skidmore Gangway 9th Lift
West Skidmore Gangway Water Level
West Skidmore Gangway 3rd Lift
East Skidmore Gangway 3rd Lift
East Skidmore Gangway 1st Lift
Water Level Skidmore Gangway
SENAWAITIS & KULACAVAGE SKIDMORE SLOPE
AIR HOLE
Bore Hole 238' Deep
ROPE HOLE
Skidmore Slope
FAULTY
East Skidmore Gangway Water Level
Resurveyed Jan-9
Resurveyed Dec. 7-'15
West 2nd Lift Skidmore Gangway
Skidmore's Slope
6th Lift Skidmore Gangway
Western Boundary of Otto Colliery
Here
FAN
WHITE ASH DRIFT
WELCH CO'S TUNNEL
To Welch Co's Tunnel
MUD DRIFT
No3 HOLMES SLOPE
SCHOOL ROW
Road to Phoenix Park
STABLE
BOILER HOUSE
BREAKER
Road to Branchdale
Bosses Houses
Ventilation Bore Hole