Short Mountain 5th Level East Rock Gangway
Short Mountain 4th Level East Rock Gangway
No 8 Slope 2d Level West Rock Gangway
No 8 Slope 2d Level West Rock Gangway
Short Mountain East Rock Gangway
No 6 Lift
No 5 Lift
No 4 Lift
Proposed Oil Pipe Line N16° 42' W
No 2 Shaft Bottom No 143 Tun
No 8 Slope 3d Level
E42
E41
E40
E39
E38
E37
E36
E35
E34
E33
E32
E31
E30
10000 E
11000 E
LITTLE VEIN
LITTLE VEIN
LITTLE VEIN
LITTLE VEIN
Big Lick Water Level Tunnel

MF
MAR 10 1972

WILLIAMSTOWN
COLL'Y.
"LITTLE Vein." WILLIAMS TWP.
DAUPHIN COUNTY, PA.
SUSQUEHANNA COLLIERIES.