


NOTE:
BREASTS LEADING TO ROBBED AREA
CLOSED TIGHT. NO AIR FLOW.

VENTILATION SYMBOLS
(where appropriate)

- Main Fan
- Auxiliary Fan
- Air Flow-Intake (Green)
- Air Flow-Return (Red)
- Stepping
- Air Bridge
- Regulator
- Man Door
- Velocity, fpm
- Quantity, cfm
- Water Gauge, in
- Escapeway
- Bleeder Evaluation Point
- Pillar Removal or Robbing
- Mine Seal
- Active Workings (Yellow)
- Curtain or Brattice
- Workings Not Surveyed
- Caved Ground

LONGITUDINAL SECTION
through the
B & B Coal Company Bottom Split Vein
situate in
Tremont Township, Schuylkill County



As per B. R. R. 74