
OTTO MINE
POOL 20
Robbed
Primrose-bed gangway
Alt. 670.4
Tunnel
Alt. 666.4
46°
Primrose-bed gangway
Alt. 901.5
Holmes-bed gangway
YORK TUNNEL
To Portal
Face unknown
Alt. 901.5
Primrose-bed gangway
Face unknown
Alt. 715 ±
Primrose-bed gangway
Alt. 1030.0
Outcrop of Holmes bed
Alt. 1020.6
Alt. 1026.9
Bootleg openings (destroyed by stripping operations)
Alt. 1032.0
Stripping
Alt. 1019.0
Alt. 1017.9
Alt. 1010.0
Alt. 1007.6
Point where water broke through
Bootleg mine where accident occurred
Alt. 1019.2
Air hole
Alt. 886.3
Alt. 885
Alt. 860.0
Water rose to this point
Alt. 766.6
Horizontal Borehole
Primrose bed
Alt. 1012.7
Alt. 991.3
Alt. 968.9
Alt. 1000.4
Stripping
Alt. 981.6
Outcrop of Primrose bed
Alt. 710±
BARRIER PILLAR
LYTTLE MINE
POOL 18
Robbed
Alt. 294.3±
Primrose-bed gangway
Alt. 289.8
Primrose-bed gangway
0
100
200
300
400
SCALE IN FEET