



COMPLAINT No. 76-10-17P
 MINE DRAINAGE AND STREAM SILTATION
 MUDDY BRANCH CREEK, VILLAGE OF BRANCHDALE
 REILLY TOWNSHIP, SCHUYLKILL COUNTY

PORTIONS TAKEN FROM OTTO COLLIERY MAP
 SCALE : 1" = 100'

Legend

② - Number and direction of photo.
 (See attached photographs)