



OTTO COLLIERY WATER OVERFLOW  
 LOCATED FROM ROUTE 209 BRANNDALE  
 SOUTHERN FIELD SCHUYLKILL COUNTY  
 1" = 100' VELLUM #1  
 COMPLAINT NO. 78-06-05P  
 RESOURCES MANAGEMENT  
 JULY 1978

*Location of the overflow*