NOTE:
BORE HOLE NUMBERS 41,44,47,54, & 73 COULD NOT BE LOCATED BECAUSE NO CASINGS WERE PROVIDED.

NO.	DATE	REVISION	APPR.

SUBMITTED
DESIGNER
APPROVED
DISTRICT ENGINEER, WILKES-BARRE
APPROVED
DIRECTOR, BUREAU OF ABANDONED MINE RECLAMATION

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
OFFICE OF RESOURCES MANAGEMENT

PROJECT NO.

HYDRAULIC BACKFILLING PROJECT
OLYPHANT PROJECT AREA
BOROUGH OF OLYPHANT
LACKAWANNA COUNTY, PENNSYLVANIA

OLYPHANT COLLIERY
No. 1 BED

DRAWN BY	DATE	DRAWING NO.
F.C.S. & A.	8/9/84	8 of 20
CHECKED BY	SCALE 1 in. = 100 ft.	

NOTE:
BORE HOLE NUMBERS 41,44,47,54, & 73 COULD NOT BE LOCATED BECAUSE NO CASINGS WERE PROVIDED.

NO.	DATE	REVISION	APPR.

SUBMITTED
DESIGNER
APPROVED
DISTRICT ENGINEER, WILKES-BARRE
APPROVED
DIRECTOR, BUREAU OF ABANDONED MINE RECLAMATION

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
OFFICE OF RESOURCES MANAGEMENT

PROJECT NO.

HYDRAULIC BACKFILLING PROJECT
OLYPHANT PROJECT AREA
BOROUGH OF OLYPHANT
LACKAWANNA COUNTY, PENNSYLVANIA

OLYPHANT COLLIERY
No. 1 BED

DRAWN BY	DATE	DRAWING NO.
F.C.S. & A.	8/9/84	9 of 20
CHECKED BY	SCALE 1 in. = 100 ft.	