



NOTE:
BORE HOLE NUMBERS 41, 44, 47, 54, & 73
COULD NOT BE LOCATED BECAUSE NO CASINGS
WERE PROVIDED.

NO.	DATE	REVISION	APPR.

SUBMITTED _____
DESIGNER _____
APPROVED _____
DISTRICT ENGINEER, WILKES-BARRE
APPROVED _____
DIRECTOR, BUREAU OF ABANDONED MINE RECLAMATION

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
OFFICE OF RESOURCES MANAGEMENT

PROJECT NO.
HYDRAULIC BACKFILLING PROJECT
OLYPHANT PROJECT AREA
BOROUGH OF OLYPHANT
LACKAWANNA COUNTY, PENNSYLVANIA

OLYPHANT COLLIERY
No. 2 BED

DRAWN BY: F.C.S. & A. DATE: 8/9/84 DRAWING NO.: 10 of 20
CHECKED BY: SCALE: 1" = 100'



NOTE:
BORE HOLE NUMBERS 41, 44, 47, 54, & 73
COULD NOT BE LOCATED BECAUSE NO CASINGS
WERE PROVIDED.

NO.	DATE	REVISION	APPR.

SUBMITTED _____
DESIGNER _____
APPROVED _____
DISTRICT ENGINEER, WILKES-BARRE
APPROVED _____
DIRECTOR, BUREAU OF ABANDONED MINE RECLAMATION

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
OFFICE OF RESOURCES MANAGEMENT

PROJECT NO.
HYDRAULIC BACKFILLING PROJECT
OLYPHANT PROJECT AREA
BOROUGH OF OLYPHANT
LACKAWANNA COUNTY, PENNSYLVANIA

OLYPHANT COLLIERY
No. 2 BED

DRAWN BY: F.C.S. & A. DATE: 8/9/84 DRAWING NO.: 11 of 20
CHECKED BY: SCALE: 1" = 100'