



Bennett Bed Outcrop

SKETCH
 SHOWING SUBSIDENCE IN ROUTE 515
 BETWEEN STA. 272 and 274 CAUSED
 BY PILLAR ROBBING IN CHECKER BED
 AT DELAWARE COLLIERY
 Scale 1"=100' October 14, 1936
 Copied from Hudson Coal Co. Map.
 October 14, 1936 Scranton Penna.

4-15-40

Oldava.

B.H. 3078 C
 Wash 21'6"
 Rock 14'6"
 No Coal

36' \sqrt{m} 3'-0" Checker
 \sqrt{m} 2'-6" Pms

Pillars being Removed

649.1
 567.0
 82.1

3-2909