



- Yellow shaded areas - Zones of Flashed Areas
- Circle with dot - Caved Voids
- Circle with cross - Tapped Voids
- Circle with horizontal lines - Dimple No 1 Vein
- Circle with vertical lines - Dimple No 2 Vein
- Circle with diagonal lines - Supply Borehole
- Circle with asterisk - Access Borehole
- Circle with triangle - Drainage Borehole
- Circle with square - Deleted Borehole

Coal conveyed by the
Schenectady Coal Co. to
the City of Scranton, Pa.
Dec. 20, 1935

Deleted Borehole
No. 1
No. 2
No. 3
No. 4
No. 5
No. 6
No. 7
No. 8
No. 9
No. 10
No. 11
No. 12
No. 13
No. 14
No. 15
No. 16
No. 17
No. 18
No. 19
No. 20
No. 21
No. 22
No. 23
No. 24
No. 25
No. 26
No. 27
No. 28
No. 29
No. 30
No. 31
No. 32
No. 33
No. 34
No. 35
No. 36
No. 37
No. 38
No. 39
No. 40
No. 41
No. 42
No. 43
No. 44
No. 45
No. 46
No. 47
No. 48
No. 49
No. 50
No. 51
No. 52
No. 53
No. 54
No. 55
No. 56
No. 57
No. 58
No. 59
No. 60
No. 61
No. 62
No. 63
No. 64
No. 65
No. 66
No. 67
No. 68
No. 69
No. 70
No. 71
No. 72
No. 73
No. 74
No. 75
No. 76
No. 77
No. 78
No. 79
No. 80
No. 81
No. 82
No. 83
No. 84
No. 85
No. 86
No. 87
No. 88
No. 89
No. 90
No. 91
No. 92
No. 93
No. 94
No. 95
No. 96
No. 97
No. 98
No. 99
No. 100

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
OFFICE OF ENGINEERING AND CONSTRUCTION
HILL SECTION - PHASE I
CITY OF SCRANTON
LACKAWANNA COUNTY
PENNSYLVANIA
NO. 2 DUNMORE VEIN
ABANDONED PINE BROOK MINE
DWG. NO. ASP 12-15