



287

Clearfield Bituminous Coal Corp.
 Plan of "B" Seam Fault
 in
 Summerhill and Allegheny Townships,
 Cambria County, Pa.
 January, 1937. Scale 1" = 3000'