

LOCATION OF GARAGES AT MILLER SHAFT

DRILL HOLE SUMMARY HARMONY NO. 1 MINE						
Drill Hole No.	Township	Surface Elevation (ft.)	Bottom of Seam Elevation (ft.)	Coal Thickness (ft.)	Perforation	Notes
H1	Portage	2219	2172	47	1	40
H2	Portage	2158	2115	43	1	36
H3	Portage	2489	2227	262	1	46
H4	Portage	2170	2050	120	1	37
H5	Portage	2405	2127	278	2	40
H6	Portage	2295	2038	257	2	35
H7	Portage	2142	-	-	No Coal	
H7A	Portage	2130	-	-	No Coal	
H8	Summerhill	2222	1939	283	1	34
H9	Summerhill	2275	-	-	No Coal	
H10	Summerhill	2445	2194	251	2	38
H11	Summerhill	2343	2082	261	1	32
H12	Summerhill	2325	2039	286	2	36
H13	Summerhill	2295	2136	159	2	36
H14	Summerhill	2295	2147	148	2	36
H15	Summerhill	2252	2058	194	2	34
H16	Summerhill	2252	2226	26	2	37
H17	Portage	2222	1939	283	1	32
H18	Summerhill	2168	1833	335	1	39
H19	Summerhill	2028	1735	293	N/A	41
H20	Summerhill	2095	1837	258	2	41
H21	Portage	2295	2043	252	1	40
H22	Portage	1869	1450	419	1	32
H23	Portage	1975	1485	490	1	42
H24	Portage	1790	1280	510	1	42
H25	Portage	1975	1624	351	0	46

