



WORKINGS PREVIOUS TO JANUARY 1, 1940

FROM JANUARY 1, 1940 TO JANUARY 1, 1941	FROM JANUARY 1, 1941 TO JANUARY 1, 1942
1941	1942
1942	1943
1943	1944
1944	1945
1945	1946
1946	1947
1947	1948
1948	1949
1949	1950
1950	1951
1951	1952
1952	1953
1953	1954
1954	1955

PREVIOUS TO JANUARY 1, 1940  
FROM JANUARY 1, 1940 TO JANUARY 1, 1955

Larson Design Group, Inc. makes no representation or warranty, expressed or implied, with regard to the accuracy, adequacy, completeness or reliability of any of the information contained herein. This map is for informational purposes only and in no way confirms the current state of the land depicted herein. Larson Design Group, Inc. hereby disclaims any and all liability for information and/or statements contained herein. Larson Design Group, Inc. shall not be liable for any damages incurred or arising as a result of reliance upon this map as well as from any errors or inaccuracies on such map.

MAP of CLAY MINE  
DANDO WORKS  
MERRILL STATION  
BEAVER COUNTY PENNA.  
THE McLain FIRE BRICK CO.  
PITTSBURGH PA.  
CERAMIC ENG. DEPT. WELLSVILLE, O.  
Scale 1" = 200 Ft. Date 7-22-59  
MINE No. 1 MAP No. MD-1-B