





 PREPARED BY:  
 AEROCON PHOTOGRAMMETRIC SERVICES, INC.  
 3209 KAISER COURT, SUITE LL-10  
 WILLOUGHBY, OHIO 44094  
 (216) 946-6277



239	238	237
246		244
255	254	253

**DILWORTH MINE**  
 DATE OF PHOTOGRAPHY: MARCH 3, 1995  
**SHEET 245**