




PREPARED BY:
 AEROCON PHOTOGRAMMETRIC SERVICES, INC.
 35000 KAISER COURT, SUITE LL-10
 WILLOUGHBY, OHIO 44094
 (216) 946-6277



266	265
274	275
284	283

DILWORTH MINE
 DATE OF PHOTOGRAPHY: MARCH 3, 1995
SHEET 275