






MATCH TO SHEET 233

MATCH TO SHEET 231




 PREPARED BY:
 AEROCON PHOTOGRAMMETRIC SERVICES, INC.
 3500 KAISER COURT, SUITE LL-10
 WILLOUGHBY, OHIO 44094
 (616) 946-6277



225	224	223
233		231
240	239	238

DILWORTH MINE
 DATE OF PHOTOGRAPHY: MARCH 3, 1995
 SHEET 232